

SUBJECT

Ordering Evaporator Coils for 3.5 Ton R407C Wall Packed Units

SCOPE

Service Contractors responsible for installation and repair.

BACKGROUND

The inlet stem location on evaporator coils for 3.5 Ton R407C units was changed to allow for better access during maintenance. When ordering replacement evaporator coils, it is critical that you verify inlet location of the failed evaporator coil before ordering. If you order the incorrect evaporator coil, you will need to re-route the refrigeration lines.

DETAILS

Prior to ordering a replacement evaporator coil, compare the stem location of the malfunctioning coil to the images below to determine the correct replacement part.

Part # 2080220290

Part # 2080401370



Feel free to contact us at ASNSupport@air-sys.com or (855) 874-5380 with any questions.

AIRSYS North America

Address: 915 De La Vina Street, Santa Barbara, CA 93101

Tel: (855) 874-5380 | **Email:** ASNSupport@air-sys.com

Web: <http://airsysnorthamerica.com>

Helpdesk: <https://support.airsysnorthamerica.com>