


WPU Wiring Diagram

Models

3R1C1DR410.230/1/60.AC
5R1C1DR410.230/1/60.AC
7E1C2DR410.230/1/60.AC
9E1C2DR410.230/1/60.AC
13E1C3DR410.230/1/60.AC



S.N	Label	Description
1	TK2	Evaporator fan overload
2	PV	Brown-out circuit used for compressor protection
3	KA3	Compressor pilot relay
4	KA4	Heater pilot relay
5	HP-1	Condenser fan switch
6	EH1-3	Electric heaters
7	EH	Crankcase heater
8	FU	Thermal fuse for heating
9	TW	Temperature switch for heating
10	PF	Air pressure differential switch
11	C	Start capacitor for compressor
12	C-1	Capacitor for condenser fan
13	LP	Low-pressure switch
14	HP	High pressure switch
15	KM2	Electric heaters AC contactor
16	KM1	Compressor AC contactor
17	MC	Compressor
18	MF2	Evaporator fan/Supply fan
19	MF-1	Condenser fan
20	FT	Compressor overload
21	TK-1	Condenser fan overload
22	YE	Air damper actuator
23	QF-1	Breaker