

WPU Wiring Diagram

Models
18E1C4DR410.230/1/60.AC

S.N	Label	Description
1	TK2	Evaporator fan overload
2	PV	Brown-out circuit used for compressor protection
3	KA3	Compressor pilot relay
4	KA4	Heater pilot relay
5	HP1	Condenser fan switch
6	EH1-3	Electric heaters
7	EH	Crankcase heater
8	FU	Thermal fuse for heating
9	TW	Temperature switch for heating
10	PF	Air pressure differential switch
11	C	Start capacitor for compressor
12	C1	Capacitor for condenser fan
13	LP	Low-pressure switch
14	HP	High pressure switch
15	KM2	Electric heaters AC contactor
16	KM1	Compressor AC contactor
17	MC	Compressor
18	MF3/MF4	Evaporator fan/Supply fan
19	MF1	Condenser fan
20	FT	Compressor overload
21	TK1	Condenser fan overload
22	YE	Air damper actuator
23	QF1	Breaker

